



Notices to the community

June 19, 2020: Update on maintenance activities at our Commerce City Refinery

As a result of maintenance being conducted in Plant 1 of our Commerce City Refinery, the plant is currently emitting elevated levels of sulfur dioxide (SO₂).

As a precaution, we are conducting air monitoring in neighboring communities until this work is complete. To date, readings obtained are below Occupational Safety and Health Administration's permissible exposure levels.

We have notified the required regulatory agencies and continue to keep them updated on the situation. We expect the maintenance work to continue through the weekend.

Our focus is on completing this work safely while minimizing impacts on our neighboring communities and the environment. We will notify stakeholders and the community once this work is complete.

If you have questions or concerns, please contact commercecityrefinery@suncor.com.

Thank you,
Suncor Energy (U.S.A.) Inc.

June 21, 2020: Suncor has completed maintenance in Plant 1 of our Commerce City Refinery

Suncor has completed maintenance in Plant 1 of our Commerce City Refinery. The units taken out of service for this work have been brought back online safely and are operating in accordance with regulatory requirements.

If you have questions or concerns, please contact commercecityrefinery@suncor.com.

Thank you,
Suncor Energy (U.S.A.) Inc.